١	MARCH	1984
---	-------	------

STAT	CHAIRMAN, CIA FINE ARIS COMMISSION
STAT	FROM: COMMISSION

RE:

UNSIGHTLY, VISUALLY DETERIORATING CONDITION OF NORTHEDET ENTRANCE

STAT	

THIS LETTER ADDRESSES SEVERAL UNGIGHTLY CONDITIONS THAT HAVE EXISTED FOR MANY MONTHS AT CIA'S OTHER "MAIN" ENTRANCE - NORTHEAST. THIS IS THE ONLY ENTRANCE OPEN ZA HOURS A DAY AND AFTER DUTY HOURS CONSTITUTES THE MAIN ENTRANCE. THE DETERORATING CONDITIONS HOUR BEEN EXACERBLYED WITH THE ADDITION OF THE CONCRETE BARRIERS GENERAL MONTHS AGO.

UNSIGHTLY CONDITIONS ARE UNACCEPTABLE AS THIS ENTEANCE SERVES MANY PEOPLE - PENTAGON "BRAGS", CONSULTANTS, REPAIR PERSONNEL FOR THE GROWING NUMBER OF COMPUTER SYSTEMS, AND OTHER PERSONNEL FROM THE GTATE DEPARTMENT AND NSA. AS SUCH THIS ENTRANCE NEEDS IMMEDIATE ATTENTION IN THE ARCAS OUTLINED BELOW. SUGARSTIONS FOR UPGRADE IMPROVEMENTS ARE USTED ALSO.

- 1. REMOVE DEBRIS AND UNUSED PARTS FROM AUTOMATIC DOOR OPENER THAT WAS INSTALLED MONTHS AGO.
- Z. POSTCHING OF CONCRETE WHERE IT IS BREAKING UP.
- 3. REMOVAL OF DETERIORITING SANDPAPER" THAT WAS ADDED TO SMOOTH CONCRETE SURFACE WHICH PLEVENTS SUPPAGE. WHEN THE SANDPAPER" WAS STUCK DOWN IT WAS WEINKLED IN PLACES. NOW, ABOUT A YEAR AFTER INSTALLATION IT REALLY LOOKS BAD. IT WAS A VERY SHODDY, QUICK-FIX GOLUTION... AND IT LOOKS IT. SOLUTION: AFTER PATCHING, REPAIRING CONCRETE (MENTIONED ABOVE) APOLY A PEDMANERY COATING OF GOME GODE THAT HAS TEXTURE WHICH WOULD BE SUP-REGISTANT.

  1 BELIEVE WE DISCUSSED THIS IDEA EARLIED AS THE MOST IDEAL SOLUTION.

  THERE ARE COMMEDIAL PRODOUTS AVAILABLE (WHICH WOULD HAVE SAVED

  THE LATINCY MONEY) THAT CAN BE PAINTED, OR SPRAYED ON... IN ESSENCE A PERMAUENT SOLUTION.
- 4. REMOVAL OF BAPRICADES AND INSTAUTION OF PLANTERS SIMILAR TO ETATE DEPARTMENT. I THINK THE LATINCY SECURITY OFFICE WILL MANT TO KEEP BARRICADES OF THIS TYPE INDEFINITELY IN PLACE-IF WERE GOING TO LIVE WITH EM LET'S DISGUISE EM.
- 5. REPLACEMENT OF CEILING THES IN "H" CORDIDOR AND EDERYWHERE ELSE THEY'VE BEEN REMOVED. "H" CORRIDOR HAS BEEN MISSING TILES FOR MONTHS.

6. I WOULD BE WILLING TO WORK ON THE EXTERIOR COMMITTED TO FOLLOW-UP ON THIS - BUT I THINK IT NEEDS TO BE BROUGHT TO THE ATTENTION OF THOSE RESPONSIBLE FOR DOING THEIR ASSECUTED TASKS. IT'S WHAT THEY'RE BEING PAID TO DO.

MUCH "STRUCING UP" IS TAKING PLACE ABOUND THE BUILDING AND THIS IS GOOD. WITH THE COMPLETION OF NORTHSIDE, PAINTING OF INTERIOR WALLS, AND NEW VIGHTING MUCH HAS BEEN DONE TO MAKE THIS A LICER PLACE TO WORK-IT HAS NOT GOVE UNNOTICED.

IF YOU NEED FUZTHER CLARIFICATION ON THESE MATTERS PLEASE FEEL FORE TO CONTACT ME, SEE YOU AT THE NEXT COMMISSION MEETING.

	THAUK	400-	
STAT			

STAT Approved For Release 2005/08/22 : CIA-RDP87-01130R000100120028-7